



TPMS

Technical Service Bulletin



Repair Procedure

RP-560-012

Applies To: Ford Motor Co. DTCs

August 21, 2012

Scope of this bulletin:

A list of Ford DTCs and their meanings.

Topics covered in this bulletin:

1. DTCs

1. DTCs:

B106A	Pressure sensor range incorrect
B106B	Pressure sensor low battery
B106D	TPMS initiators not configured
B2477	Module configuration mismatch
B2868	LF sensor fault
B2869	RF sensor fault
B2870	RR sensor fault
B2871	LR sensor fault
B2872	Pressure sensor fault
B287A	TPMS Fault
C2780	ECU in manufacture mode
U0155	Loss communication with inst cluster
U0155	Loss of Comms. Is not covered on every vehicle.
B1342	ECU is defective is on the. Ranger 4x4 and a couple others.