



TPMS

Technical Service Bulletin



Repair Procedure

RP-561-012

Applies To: General Motors DTCs

August 21, 2012

Scope of this bulletin:

A list of GM DTCs, and their definitions.

Topics covered in this bulletin:

1. DTCs

1. DTCs:

C0551	TPMS Receiver Module Internal Fault
C0569-00	System Configuration Error
C0750	Transmitter Battery Voltage Too Low
C0755	Transmitter Battery Voltage Too Low
C0760	Transmitter Battery Voltage Too Low
C0765	Transmitter Battery Voltage Too Low
C0750-00	Left Front Low Tire Pressure Sensor
C0755-00	Right Front Low Tire Pressure Sensor
C0760-00	Left Rear Low Tire Pressure Sensor
C0765-00	Right Rear Low Tire Pressure Sensor
C0750-08	Left Front Low Tire Pressure Sensor Signal Invalid
C0755-08	Right Front Low Tire Pressure Sensor Signal Invalid
C0760-08	Left Rear Low Tire Pressure Sensor Signal Invalid
C0765-08	Right Rear Low Tire Pressure Sensor Signal Invalid
C0751	Reception Failure
C0756	Reception Failure
C0761	Reception Failure
C0766	Reception Failure
C0774	Low Tire Pressure System Performance
C0775	Low Tire Pressure System Sensors Not Learned
C0775	Air Pressure Warning
C0776	Air Pressure Warning
C0777	Air Pressure Warning
C0778	Air Pressure Warning
C0779	Unregistered ID Code
U2149	Lost Communication With Tire Pressure Monitor (TPM) System