



Software Update



SU-R53.6-016

Applies To: R53.6 Software Release

March 18, 2016

Scope of this bulletin:

Bartec USA launches Software Release R53.6. This patch fix is released to deal with the sensor manufacture making a running change to the 52933-3X200 TPMS sensor used on Hyundai/Kia. Bartec has made adjustments to the sensor activation and decode of these sensors.

Feature	Industry Exclusive	Benefit	400	400Plus	400SD	500	300PRO	400PRO
Activation and Decode of 52933-3X200 TPM Sensor		Changed to reliably activate the sensor as a result of the running changes by the sensor manufacture	✓	✓	✓	✓	✓	✓