RiteSensor®



Fitment Bulletin



Toyota	Tundra	2023	OBDII
MAKE	MODEL	YEAR	RELEARN



Set up Tech600Pro using VINdicate®
Check for TPMS related DTC's.



Verify malfunctioning sensor[s] by testing with the Tech600Pro.



Replace malfunctioning sensor[s] with the Rite-Sensor[s]®.Install wheel[s] back on to the Tundra.



Power up the Tech600Pro and once again connect the VCI and set up tool. Select TPMS, then RITE-SYNC® RELEARN and follow the tool prompts



RITE-SYNC®programs and relearns at the same, for a fast and accurate repair.



The process is complete by immediately driving the vehicle or activating the sensors a second time. The TPMS Light should be off at this time.