# Software Update

| TSB # | SUBJECT | DATE |
|---|---|---|
| SRB-R58.1 | Tool Software Update 58.1 Software Patch | Nov 19, 2018 |
| **S/W VERSION** | **TOOL[S] AFFECTED** | |
| 58.1 | Tech400SD, Tech500, Tech300Pro, Tech300ProC and Tech400Pro. See chart for specific improvements to the respective tools. | |

**OVERVIEW**

| Feature | Exclusive | Benefit | 400SD | 500 | 300PRO | 300PROC | 400PRO |
|---|---|---|---|---|---|---|---|
| Bug Fix: Subaru OBD COMMS | | Corrected OBD COMMS for Subaru vehicles not working in R58.0 | ✓ | ✓ | ✓ | ✓ | ✓ |
| Bug Fix: 2018 Toyota Tacoma Coverage | | Corrected OE and Aftermarket Sensor coverage for the 2018 Toyota Tacoma | ✓ | ✓ | ✓ | ✓ | ✓ |
| Bug Fix: Placard Pressure Change coverage updated | | Corrected the Make-Model-Year list for Placard Change Support | | ✓ | | | ✓ |
| Bug Fix: JohnDow DVT sensor coverage updated | | Corrected coverage for JohnDow DVT Sensors. | ✓ | ✓ | ✓ | ✓ | ✓ |
| Bug Fix: NAPA QWIK sensor coverage updated | | Added NAPA QWIK sensor coverage back to the 400SD tools. | ✓ | | | | |
| Coverage: BMW 2018/10 OE Part Number 36 10 6 887 140 | | Added sensor coverage with qualifiers to 2018 Early/Late and 2019 BMW Models. | ✓ | ✓ | ✓ | ✓ | ✓ |
| Bug Fix: Toyota Prius listed twice | | Removed 1 selection from vehicle listing | ✓ | ✓ | ✓ | ✓ | ✓ |
| Bug Fix: Toyota/Lexus Loop Reset (ECU Reset) | | Process worked on R58.0, but would show a "failure". Corrected software to correctly indicate a successful function. | ✓ | ✓ | ✓ | ✓ | ✓ |
| Bug Fix: Hyundai/Kia COMMS | | Corrected OBD COMMS for Hyundai/Kia vehicles not working in R58.0 | ✓ | ✓ | ✓ | ✓ | ✓ |
| Updated EZ-sensor coverage | | Added support for Schrader EZ-sensor | ✓ | ✓ | ✓ | ✓ | ✓ |

**\*\*NOTE: R58.1 will list placard coverage for 2010-12 Chevrolet Impala and 2014-18 Ram 3500 SRW. These are not supported in this release. To see what placard is supported, see chart below.**

### Bug Fix: Subaru OBD COMMS

Corrected issues in R58.0 for earlier Subaru vehicles where OBD COMMS did not work in R58.0.

### Bug Fix: 2018 Toyota Tacoma Coverage

Corrected OE and aftermarket sensor coverage for the 2018 Toyota Tacoma.

# Software Update

## Bug Fix: Placard Pressure Change

Coverage corrected to released vehicles. See Listing below for current coverage.

| Year | Make | Model | Year | Make | Model |
|---|---|---|---|---|---|
| 2017 | Cadillac | Escalade | 2008 | Chevrolet | Suburban |
| 2016 | Cadillac | Escalade | 2016 | Chevrolet | Tahoe |
| 2015 | Cadillac | Escalade | 2015 | Chevrolet | Tahoe |
| 2014 | Cadillac | Escalade | 2014 | Chevrolet | Tahoe |
| 2013 | Cadillac | Escalade | 2013 | Chevrolet | Tahoe |
| 2013 | Chevrolet | Avalanche | 2012 | Chevrolet | Tahoe |
| 2012 | Chevrolet | Avalanche | 2011 | Chevrolet | Tahoe |
| 2011 | Chevrolet | Avalanche | 2010 | Chevrolet | Tahoe |
| 2010 | Chevrolet | Avalanche | 2008 | Chevrolet | Tahoe |
| 2017 | Chevrolet | Equinox | 2017 | Chevrolet | Traverse |
| 2016 | Chevrolet | Equinox | 2016 | Chevrolet | Traverse |
| 2015 | Chevrolet | Equinox | 2015 | Chevrolet | Traverse |
| 2012 | Chevrolet | Equinox | 2014 | Chevrolet | Traverse |
| 2016 | Chevrolet | Express | 2013 | Chevrolet | Traverse |
| 2015 | Chevrolet | Express | 2012 | Chevrolet | Traverse |
| 2014 | Chevrolet | Express | 2013 | Dodge | RAM 1500 |
| 2013 | Chevrolet | Express | 2009 | Dodge | RAM 1500 |
| 2012 | Chevrolet | Express | 2008 | Dodge | RAM 1500 |
| 2011 | Chevrolet | Express | 2007 | Dodge | RAM 1500 |
| 2010 | Chevrolet | Express | 2013 | Dodge | RAM 2500 |
| 2011 | Chevrolet | HHR | 2013 | Dodge | RAM 3500 SRW |
| 2010 | Chevrolet | HHR | 2013 | Ford | F-150 |
| 2017 | Chevrolet | Silverado 1500 | 2012 | Ford | F-150 |
| 2016 | Chevrolet | Silverado 1500 | 2011 | Ford | F-150 |
| 2015 | Chevrolet | Silverado 1500 | 2012 | Ford | F-250 SD |
| 2014 | Chevrolet | Silverado 1500 | 2011 | Ford | F-250 SD |
| 2013 | Chevrolet | Silverado 1500 | 2017 | GMC | Acadia |
| 2012 | Chevrolet | Silverado 1500 | 2016 | GMC | Acadia |
| 2011 | Chevrolet | Silverado 1500 | 2015 | GMC | Acadia |
| 2010 | Chevrolet | Silverado 1500 | 2014 | GMC | Acadia |
| 2009 | Chevrolet | Silverado 1500 | 2013 | GMC | Acadia |
| 2008 | Chevrolet | Silverado 1500 | 2012 | GMC | Acadia |
| 2016 | Chevrolet | Silverado 2500 | 2011 | GMC | Acadia |
| 2015 | Chevrolet | Silverado 2500 | 2010 | GMC | Acadia |
| 2014 | Chevrolet | Silverado 2500 | 2009 | GMC | Acadia |
| 2013 | Chevrolet | Silverado 2500 | 2015 | GMC | Savana |
| 2012 | Chevrolet | Silverado 2500 | 2014 | GMC | Savana |
| 2016 | Chevrolet | Silverado 3500 | 2013 | GMC | Savana |
| 2015 | Chevrolet | Silverado 3500 | 2012 | GMC | Savana |
| 2014 | Chevrolet | Silverado 3500 | 2011 | GMC | Savana |
| 2013 | Chevrolet | Silverado 3500 | 2010 | GMC | Savana |
| 2012 | Chevrolet | Silverado 3500 | 2017 | GMC | Terrain |
| 2016 | Chevrolet | Suburban | 2016 | GMC | Terrain |
| 2015 | Chevrolet | Suburban | 2015 | GMC | Terrain |
| 2014 | Chevrolet | Suburban | 2012 | GMC | Terrain |
| 2013 | Chevrolet | Suburban | 2011 | GMC | Terrain |
| 2012 | Chevrolet | Suburban | 2010 | GMC | Terrain |
| 2011 | Chevrolet | Suburban | 2013 | Jeep | Wrangler |
| 2010 | Chevrolet | Suburban | 2010 | Jeep | Wrangler |
| 2009 | Chevrolet | Suburban | | | |

## Bug Fix: JohnDow DVT sensor coverage updated

Corrected coverage for JohnDow DVT Sensors.

# Software Update

**Bug Fix: NAPA QWIK Sensor coverage updated**

Added NAPA QWIK sensor coverage back to the 400SD tools.

**Bug Fix: BMW 2018/10 OE Part Number 36 10 6 887 140**

Added sensor coverage with qualifiers to 2018 Early/Late and 2019 BMW Models.

**Bug Fix: Toyota Prius listed twice**

Removed 1 selection from vehicle listing.

**Bug Fix: Toyota/Lexus Loop Reset (ECU Reset)**

Process worked on R58.0, but tool showed a "failure" message. R58.1 has corrected this false feedback to correctly indicate a successful function.

**Bug Fix: Hyundai/Kia COMMS**

Corrected OBD COMMS for Hyundai/Kia vehicles not working in R58.0

**Bug Fix: Updated EZ-sensor coverage**

Added coverage for Schrader EZ-sensor.