

Base

Power Button

after 1 minute

auto off

Set Zero

button

place base against flat

surface, push depth bar

till pin stops, press ZERO