

BARTEC TPMS PROCEDURE

Make	Model(s)	Year(s)	Tool(s)	Software Version
See List Below	See List Below	08-09	All	N/A
Description				
TSB – Low Pressure Light stays on even though pressures are ok				

Background

If the following vehicles TPM light comes on showing low pressure, but all the sensors are working, have been programmed to the vehicle, and the pressures are set at placard, the vehicle may need to have the Remote Control Door Lock Receiver reprogrammed. This will need to be done by the dealership.

Vehicles Affected:

2008	2009	Buick	Lucerne
2008	2009	Cadillac	CTS, DTS, Escalade, Escalade ESV, Escalade EXT
2008	2009	Chevrolet	Avalanche, Silverado, Suburban, Tahoe
2008	2009	GMC	Sierra, Sierra Denali, Yukon, Yukon Denali, Yukon XL, Yukon Denali XL
2008	2009	Hummer	H2
	2009	Saturn	Vue
<i>Vehicle Build Dates Jan1, 2008 - Aug 15, 2008</i>			

Please contact Bartec with any questions.