



**Software Update** 

TSB #	SUBJECT	DATE
SRB-V2.4-017	Tool Software Update V2.4	February 3, 2017
S/W VERSION[S]	TOOL[S] AFFECTED	
V2.4.0	See chart below	

**Overview**

Software Update V2.4 for the Tech 200. This patch update improves the process for EZ-sensor programming.

Feature	Industry Exclusive	Benefit	TECH200
Bug Fix: Improved EZ-sensor programming		Improved handling of EZ-sensor programming for more consistent programming process	✓

**Bug Fix:**

The process for programming EZ-sensor has been made more repeatable and consistent by improving the wireless programming and decoding of the sensor.