





# **General Information**

TSB #	SUBJECT		DATE
GI-27236-017	TPMS LIGHT ON FOLLOWING: Relearn: Wireless Devices Connected AND/OR charging in vehicle		9/27/2017
MAKE[S]	MODEL[S]	YEAR[S]	
Any	Any	Any	
S/W VERSION[S]	TOOL[S] AFFECTED		
N/A	ALL TPMS TOOLS		

# **Overview**

Wireless devices connected and/or charging in the vehicle may cause the TPMS light to stay on before or after completing a TPMS Relearn on a vehicle.

# Cause

Wireless devices and sensors use RF (Radio Frequencies'). This RF can interfere with each other and this can cause the TPMS light to stay ON.

### Example

2016 Nissan Altima. After completing the OBD relearn, the TPMS Light was still flashing. There was a phone connected to the vehicle via Bluetooth. Once the phone was disconnected, the TPMS light went off.

### **Problem Resolution**

- 1.) Remove/Disconnect any Wireless Devices from the vehicle.
- 2.) Remove any USB cords from the vehicle.
- 3.) Complete a TIRE PRESSURE LEARN using the Bartec tool.
- 4.) Verify that the TPMS light is turned OFF.

If the issue continues after completing the steps above please call Bartec Technical Support at (866)407-8767 to further assist you with the issue.

Bartec USA Technical Support: [866]407-8767







Bartec makes commercially reasonable efforts to provide accurate and complete data in connection with our tools and our website, but the volume of data compiled and the variety of sources from which the data comes makes it impossible to warrant full accuracy or completeness of any kind. AS A RESULT, BARTEC DOES NOT WARRANT, AND SPECIFICALLY DISCLAIMS ANY WARRANTY, THAT OUR TOOLS, WEBSITE, AND/OR THE CONTENT CONTAINED THEREIN IS ACCURATE OR COMPLETE.



