



Software Update

TSB #	SUBJECT	DATE
SRB-R55.1	Tool Software Update R55.1	February 14, 2017
S/W VERSION[S]	TOOL[S] AFFECTED	
55.1.0	See chart below	

Overview

Software Update Release 55.1 for Bartec USA TPMS Tools. This software improves the programming process for the Huf IntelliSens sensor, specifically for the 433 MHz applications.

This software improvement affects programming the Huf Part Number 4030/4031

Feature	Industry Exclusive	Benefit	400	400Plus	400SD	500	300PRO	400PRO
Improved Huf 433 MHz Programming		Improved reliability of programming the Huf 433 MHz sensors (Part Number 4030/31)			✓	✓	✓	✓