







TSB#	SUBJECT	DATE	
SRB-R57.1	Tool Software Update R57.1	January 26, 2018	
S/W VERSION[S]	TOOL[S] AFFECTED		
57.1	See Below		

OVERVIEW

This software update increases coverage, opens additional placard adjusting coverage, and improves aftermarket sensor functionality and coverage.

Feature	Exclusive	Benefit	400SD	500	300PRO	400PRO
Added Placard Coverage	$\qquad \qquad \bigstar$	2014 GMC Sierra 2500 and 3500		✓		✓
Alligator Sens-it Coverage		Updated Alligator Sens-it coverage	✓	✓	✓	✓
JS Steelman Select Coverage		Added coverage for JS Products Steelman Select programmable sensors	✓	✓	✓	✓
MY2018 Infiniti		Updated 2018 Infiniti model coverage for carryover vehicles: Q50, Q60, Q70, Q70L, QX30, QX60	✓	√	✓	✓
2018 Infiniti QX80		New TPMS Sensor and OBD COMMS added for 2018 QX80	✓	√	✓	✓
2018 Audi TT RS		Added coverage for 2018 Audi TT RS for Direct TPMS	<	✓	✓	✓
2018 Genesis G80		Added sensor coverage for 2018 Genesis G80	✓	✓	✓	✓
BMW Coverage		Updated coverage for the 2016-2017 BMW X1 and relearn for the 2012-2017 BMW X3	✓	√	✓	✓
2018 Subaru Forester		Extended coverage for the Subaru Forester through 2018	✓	✓	✓	✓
Mercedes Coverage		Updated coverage for 200-2006 Mercedes S430/S500	✓	✓	✓	✓
Mitsubishi COMMS		Improved the COMMS process for Assisted Relearn Mitsubishi Vehicles	✓	✓	✓	✓
Ford F-150 PAL Coverage		Added support for 433 PAL sensors on the 2018 Ford F-150	✓	✓	✓	✓
Mini Coverage		Updated sensor coverage for Mini	✓	✓	✓	✓
Honda Coverage		Updated OE sensor coverage for 2016- 17 Honda Ridgeline. Updated coverage Honda FCX Clarity.	✓	✓	✓	✓
Kia Forte COMMS		Corrected COMMS Coverage on the 2014-2015 Kia Forte	✓	✓	✓	✓
Toyota COMMS		Bug Fix: updated Toyota COMMS	✓	✓	✓	✓

©2018, Bartec USA, LLC

























Added Placard Coverage

Added coverage to adjust the Placard values on the 2014 GMC Sierra 2500 and 3500.

JS Steelman

Added more coverage for JS Products Steelman Select programmable sensors.

Alligator Sens-it Coverage

Updated the coverage for the Alligator Sens-it aftermarket programmable sensor.

Added MY2018 Infiniti

Updated 2018 Infiniti model coverage for Sensor Testing, OBD Diagnostics, and OBD relearn carryover vehicles: Q50, Q60, Q70, Q70L, QX30, and QX60.

2018 Infiniti QX80

Added the new TPMS Sensor and OBD COMMS (Diagnostics and Relearn) for the 2018 QX80

2018 Audi TT RS

Added coverage for 2018 Audi TT RS for Direct TPMS sensors. This covers Sensor Testing and the Drive Relearn for this vehicle.

2018 Genesis G80

Added TPM sensor test coverage for 2018 Genesis G80

BMW Coverage

Updated coverage for the 2016-2017 BMW X1 and relearn for the 2012-2017 BMW X3. The X3 BMW is supported for Bonus OBD Relearn.

2018 Subaru Forester

Extended coverage for the Subaru Forester through 2018 for Sensor Testing, OBD Diagnostics, and OBD Relearn.

Mercedes Coverage

Updated sensor coverage for 2000-2006 Mercedes S430/S500

Mitsubishi COMMS

Improved the OBD Relearn COMMS process for Assisted Relearn Mitsubishi Vehicles

Ford F-150 PAL Coverage

Added support for 433 PAL TPM sensors on the 2018 Ford F-150. The 2018 F-150 will be listed on the tool with a qualifier of 315MHz or 433MHz.

Mini Coverage

Updated TPM sensor coverage for Mini vehicles.

Updated OE TPM sensor coverage for 2016-17 Honda Ridgeline. Updated TPM sensor coverage Honda FCX Clarity.

Kia Forte

Corrected COMMS (Diagnostics and Relearn) Coverage on the 2014-2015 Kia Forte

Toyota COMMS

Bug Fix: corrected issue with OBD COMMS during Toyota Relearn where tool would re-boot.















