





Software Update

TSB #	SUBJECT	DATE of RELEASE	
SRB-R60.0	Tool Software Update 60.0	September 13, 2019	
S/W VERSION	TOOL[S] AFFECTED		
60.0	Tech400SD, Tech500, Tech300Pro, Tech300ProC and Tech400Pro. See OVERVIEW chart for specific improvements to the respective tools.		

OVERVIEW

Feature	Exclusive	Description	400SD	500	300PRO	300PROC	400PRO
Bartec RITE-SENSOR® TPMS Sensor program	\bigstar	Added functionality for single SKU 315/433MHz RITE-SENSOR [®] Programmable TPMS sensor including OE sensor replacement service kit part numbers.	~	~	~	~	✓
VINdicate [®] coverage	\bigstar	Coverage added for VINdicate [®] allowing the technician to configure the Make-Model-Year automatically through the OBDII.		~		~	~
Schrader EZ-sensor [®] TPMS		Updated coverage for Schrader EZ-sensor [®] TPMS sensors.	✓	✓	~	✓	✓
Model Year 2020 Update		Added support for Model Year 2020 vehicles.	~	~	~	~	~
Huf IntelliSens [®] TPMS		Updated coverage for Huf IntelliSens [®] TPMS sensors.	~	~	~	~	~
OBD Coverage Increased		23% increase over previous software versions in OBD COMMS Coverage for Diagnostics and Relearns	~	~		~	~
Coverage Fix: 2018-19 Lexus GX460		Updated coverage on the OE sensor for the 2018-19 Lexus GX460	~	~	1	~	~
Bug Fix: REDI-SENSOR™ High Pressure Ford		Corrected issues with REDI-SENSOR TM decode with Ford High Pressure applications such as E-250	~	~	✓	~	~
Coverage: QWIK SENSOR/Orange Universal TPM Sensor		Coverage for these aftermarket sensors has been dropped from the 400SD. Orange OPPS, Standard OE Match, Orange Universal, and QWIK sensor	~				

NOTE: Bartec is committed to maintaining sensor coverage on major aftermarket sensors.

Bartec RITE-SENSOR® TPMS Sensor program

Added functionality for single SKU 315/433MHz RITE-SENSOR® Programmable TPMS sensor including OE sensor replacement service kit part numbers.

VINdicate[®] Coverage

Coverage added for VINdicate® allowing the technician to configure the Make-Model-Year automatically through the OBDII. Selecting Make, Model and Year based on anything other than the VIN can lead to errors in diagnosis, even wrong

©2019, Bartec USA, LLC

AALA OODEX 🥹 📰 🖻 🔛 🗰 etrico 🚋 iatro 🖅 😂 🦛 Semp tigo Euro

Bartec USA Technical Support: [866]407-8767 Bartec makes commercially reasonable efforts to provide accurate and complete data in connection with our tools and our website, but the volume of data compiled and the variety of sources from which the data comes makes it impossible to warrant full accuracy or completeness of any kind. AS A RESULT, BARTEC DOES NOT WARRANT, AND SPECIFICALLY DISCLAIMS ANY WARRANTY, THAT OUR TOOLS, WEBSITE, AND/OR THE CONTENT CONTAINED THEREIN IS ACCURATE OR COMPLETE.







Software Update

sensor programming. VINdicate[®] is the unique process by which the VIN is detected and decoded for the right Make, Model and Year, and used to quickly set up the Bartec TPMS Tool for service. Only Bartec Tools have VINdicate[®]

Schrader EZ-sensor® TPMS

Increased coverage for Schrader EZ-sensor[®] TPMS. For more information regarding this sensor, visit <u>www.schradersensors.com</u>

Huf IntelliSens® TPMS

Updated coverage for Huf IntelliSens[®] TPMS sensors. For more information regarding this sensor, visit <u>www.intellisens.com</u>

Model Year 2020 Update

Model Year 2020 support for the following manufactures:

Acura	Fiat	Lexus	RAM
Alfa Romeo	Ford	Lincoln	Rolls-Royce
Alpina	Freightliner	Lotus	Smart
Aston Martin	Genesis	Maserati	Subaru
Audi	GMC	Maybach	Tesla
BMW	Honda	Mazda	Toyota
BMW Motorcycles	Hyundai	McLaren	Volkswagen
Buick	Infiniti	Mercedes-Benz	Volvo
Cadillac	Jaguar	Mercedes-Benz AMG	
Chevrolet	Jeep	Mini	
Chrysler	Kia	Mitsubishi	
Dodge	Lamborghini	Nissan	
Ferrari	Land Rover	Porsche	

OBD Coverage Increased

23% increase in OBD COMMS Coverage for Diagnostics and Relearns

COMMS coverage now includes:

Acura	Honda	Nissan
Alfa Romeo	Hyundai	Pontiac
BMW	Infiniti	RAM
Buick	Jaguar	Scion
Cadillac	Jeep	Subaru
Chevrolet	Kia	Suzuki
Chrysler	Land Rover	Toyota
Dodge	Lexus	Volkswagen
Ford	Lincoln	Volvo
Freightliner	Mercedes-Benz	
GMC	Mitsubishi	

Coverage Fix: 2018-19 Lexus GX460

Updated coverage on the OE sensor for the 2018-19 Lexus GX460

Bug Fix: REDI-SENSOR[™] High Pressure Ford

©2019, Bartec USA, LLC

Bartec USA Technical Support: [866]407-8767

Bartec makes commercially reasonable efforts to provide accurate and complete data in connection with our tools and our website, but the volume of data compiled and the variety of sources from which the data comes makes it impossible to warrant full accuracy or completeness of any kind. AS A RESULT, BARTEC DOES NOT WARRANT, AND SPECIFICALLY DISCLAIMS ANY WARRANTY, THAT OUR TOOLS, WEBSITE, AND/OR THE CONTENT CONTAINED THEREIN IS ACCURATE OR COMPLETE.







Software Update

Corrected issues with REDI-SENSOR[™] decode with Ford High Pressure applications such as E-250

©2019, Bartec USA, LLC Bartec USA Technical Support: [866]407-8767 Bartec makes commercially reasonable efforts to provide acc



Bartec makes commercially reasonable efforts to provide accurate and complete data in connection with our tools and our website, but the volume of data compiled and the variety of sources from which the data comes makes it impossible to warrant full accuracy or completeness of any kind. AS A RESULT, BARTEC DOES NOT WARRANT, AND SPECIFICALLY DISCLAIMS ANY WARRANTY, THAT OUR TOOLS, WEBSITE, AND/OR THE CONTENT CONTAINED THEREIN IS ACCURATE OR COMPLETE.