



## Tool Software Update

### Coverage Update:

Increased Coverage on the following manufactures below. To see the full list of vehicle coverage please visit:

<https://www.bartecusa.com/tpms-tool-coverage-charts>

Make	Make	Make	Make	Make
Acura	BMW	Cadillac	Chevrolet	Dodge
Ford	GMC	Honda	Hyundai	Kia
Lexus	Lincoln	Lotus	Mazda	Mercedes
Mini	Nissan	RAM	Subaru	VinFast
Volkswagen	Volvo			

### Added Coverage for RITE-SENSOR®:

Added RITE-SENSOR® coverage for both the RS-1000® and RS-2000®. Please view your applicable tool coverage chart for the RITE-SENSOR® part that can be used.

Make	Model	Year Range	Qualifier	Make	Model	Year Range	Qualifier
Acura	ZDX	2024-2025	None	Chevrolet	Blazer EV	2024	None
Chevrolet	Silverado Trailer	2023-2024	None	Dodge	Challenger	2024	None
Cadillac	Celestiq	2025	None	Cadillac	Escalade IQ	2025	None
GMC	Sierra Trailer	2023-2024	None	Honda	Pilot Touring	2009-2015	None
Honda	Prologue	2009-2015	None	Hyundai	Kona	2024-2025	None
Kia	EV9	2024-2025	None	Lexus	GX550	2024-2025	None
Lexus	RZ	2023-2025	None	Lotus	Eletre	2024-2025	None
Mercedes-Benz	CLE Class	2024-2025	None	Mercedes-Benz	GLA Class	2024-2025	None
Mercedes-Benz AMG	AMG CLE Class	2024	None	Mercedes-Benz AMG	GLA Class	2024	None
Volvo	EX30	2024-2025	None	Volvo	EX90	2024-2025	None

### Added OBD Coverage:

Added OBD Coverage for the following MMYs. Please view your applicable tool coverage chart for OBD further information.

Make	Model	Year Range	Qualifier	Make	Model	Year Range	Qualifier
Cadillac	Escalade IQ	2025	None	Chevrolet	Trailblazer	2025	None
Ford	Bronco Sport	2025	None	Ford	EcoSport	2021-2022	Snap In
Ford	EcoSport	2021-2022	Clamp In	Ford	Escape	2025	None
Ford	Explorer	2024	315/433	Ford	Explorer	2025	None
Ford	Maverick	2024-2025	315/433	Ford	Transit Cargo & Wagon	2025	Single/Dual RW
Lincoln	Aviator	2025	None	Nissan	Ariya	2025	None

### Added Placard Coverage:

Added Placard Coverage for the following MMYs:

Make	Model	Year Range	Qualifier	Make	Model	Year Range	Qualifier
Cadillac	Escalade IQ	2025	None	Chevrolet	Trailblazer	2025	None
Ford	Escape	2025	None	Ford	Explorer	2024	315/433
Ford	Explorer	2025	None	Ford	Maverick	2024-2025	315/433
Ford	Transit Cargo & Wagon	2025	Single/Dual RW	Lincoln	Aviator	2025	None

## Tool Software Update

### Tread-Rite® Support:

Bartec is adding support for the Tech600Pro and Tech550Pro to be wirelessly connected via Bluetooth® to the Tread-Rite® inspection tool. Users will now be able to complete a tread and tpms vehicle inspection report or a tread inspection.

**Complete Vehicle Inspection within a MMY (Make, Model, Year). Print a complete vehicle inspection report using TPMS Desktop:**

- OBD Diagnostics
- Test Sensors
- Tread Inspection

The screenshots show the following screens:

- Service Menu:** Vehicle Inspection, Relearn, Programmable Sensors, Placard Pressure, Vehicle Data, Technical Information.
- Vehicle Inspection Menu:** OBD Diagnostics, Test Sensors, Tread Inspection.
- OBID Results:** View DTCs (1), View VIN, View Sensor IDs, View Placard Settings.
- Vehicle Inspection (F-150, 22):**

Pos.	PSI	Bat.	Status
LF	35	OK	✓
RF	35	OK	✓
RR	35	OK	✓
LR	35	Low	✗

ID: 8000A043 Temp: 72 F Mode: ToolLF
- Vehicle Inspection (F-150, 22):**

Pos.	Out.	Cen.	Inn.
LF	9.1	8.4	8.3
RF	8.3	8.2	8.3
RR	8.3	8.4	8.6
LR	8.4	8.6	8.3

TDR100: 64F587D92E0299 Press MENU for more options
- Printed Report:**

Customer: Matt Hitchcock Registration: Vehicle: Ford F-150 2022  
 Date: 2/27/2024 1:30:00 PM Mileage: 12055  
 Reference: Tire Type: Standard

TPMS Sensor Data:

  - Sensor 1610653760: LF, 35.0 PSI, OK
  - Sensor 1610653761: RF, 35.0 PSI, Pass
  - Sensor 1610653763: RR, 35.0 PSI, Low
  - Sensor 1610653762: LR, 35.0 PSI, Pass

Tire Tread Status Legend:

  - OK: 7/32" and up
  - Replace Soon: 3/32" to 6/32"
  - Replace Today: 2/32" and below
  - Tire OK for use.
  - Tire is worn. Consider purchasing new tires.
  - Tire is no longer safe. Tire must be replaced.

### Quick Tread Service can be found on the main menu of your Tech600Pro® or Tech550Pro®:

The screenshots show the following screens:

- Home Menu:** New Service, Resume Service, History, Toolkit, Settings, Tread Inspection.
- Tread Inspection (F-150, 22):**



Pos.	Out.	Cen.	Inn.
LF	3	2	3
RF	6	4	5
RR	11	12	9
LR	0	2	4

TDR100: 64D37B69399D19 Press MENU for more options

## Tool Software Update


### Improved Wifi Messaging:

Bartec has improved the user experience WiFi updating by adding more messages. Users may now experience “Server is currently busy and cannot process the request at this time, please try again later” this is due to the high number of downloads at a given time. Or if there is a concern with the users WiFi it will now display “Failed to connect to the WiFi network. Please ensure that you are within range of your router and that it is configured correctly”.




### Modified WiFi Connection Screen:

Bartec has modified the connected WiFi screen to help the users from accidentally forgetting the network and having to reconnect. Forget will now be listed second.






Previous HMI



New HMI

### Added Tool Off Setting:

Previously the Tech450Pro did not have the ability to change the amount of time before it automatically shuts off, this was due to keeping it like the Tech400Pro.



### Updated Aftermarket Sensor Coverage:

Updated aftermarket sensor coverage for Huf® (BHSens), IntelliSens UVS® and Schrader (Sensata) EZ-Sensor®.